

Crew of Aircraft B-47E #53-1976A

Captain Earl E. Kechler, Air Craft Commander.

Captain Charles S. Woodruff, Co-Pilot.

Captain Bruce M. Kalka, Navigator.



Area Where Nuclear Weapon was Dropped

N

Bldg "n"

Bldg "m"

Bldg "k"

Bldg "j"

behind

Bldg "d"

9-11G 804PL 12MAR58 BOMB DAMAGE



Bldg "a"

N


Swampy  
area

Bomb Crater

Bldg "b"

Bldg "c"

9-126 804PL 12 MAR 58 BOMB DAMAGE



Bldg "f" from Bldg "a"

N


Bldg "b"

Bldg "c"

9-66 804PL 12MAR58 BOMB DAMAGE

FRONT VIEW  
WALTER GREGG HOME





9-2G 804PL 12MAR58 BOMB DAMAGE



BACK VIEW

WALTER GREGG HOME



9-96 804 PL 12MAR58 BOMB DAMAGE ●●●

GARAGE

WALTER GREGG HOME






Fig 11

6948 12MAR58 BOMB DAMAGE

CAR OF WALTER GREGG






Bldg "a" Rear View

9-36 804PL 12MAR58 BOMB ~ DAMAGE



DINING ROOM

WALTER GREGG HOME



The woman was working in  
this area

Room

EVIDENCE. BOX

KITCHEN

WALTER GREGG HOME






Bldg 10 Kitchen

956 BOMBED 12 MAR 58 BOMB DAMAGE

BEDROOM

WALTER GREGG HOME



Bldg

room

D-4G

PR

BOMB DAMA

MOUNT MIZPAH BAPTIST CHURCH





Original po

Church chimney

1912

INTERIOR MOUNT MIZPAH BAPTIST CHURCH

Bldg 1 Interior view

BOMB DAMAGE

9-10G 8Q4 PL 12MAR58



52

PORTRAITS

INTERIOR OF BOMB BAY OF AIRCRAFT



A

BROKEN  
ROLLER



W11 8712

3-5-80


3-5-80



3-5 804 P 15 MAR 80



DAMAGE  
BY FINS



8-4 804 PL 15 MAR. 58

B

R BOMB BAY  
DOOR

Roller →

8-2 804 PL 15 MAR 58


C

ALL HANDLING REQUIRED  
CLEARANCE WITH PART 40 & 62 AIR 52



D

9-1 804 PL 15 MAR. 58.







RELEASE SYSTEM  
PRESSURE GAUGE

Hoist


146191

GROUP 1A CATAL  
CLOSE FOR EXHAUST  
CROSS HEATING ONLY  
UPPER CURTAIN CLOSED  
AT ALL TIMES

OPERATING DOOR









8-1804715 MAR 59

CS



8-20-2004 PJ 15 MAR 58





EMERGENCY  
RELEASE  
HANDLE

80000115MAR58



80494 15 MAR 58